

1. Installation Test

1.1 Windows 10

Configuration

CPU	Intel(R) Atom(TM) Processor E3950 @ 1.60GHz	
Memory	Transcend TS9W9SESD-I DDR3L-1600 8GB [SEC chipset]	
HDD	Transcend TS64EPTMM16-I 64GB	
DVD-ROM	Pioneer DVR-XU01T	
Power Supply	FSP GROUP INC. model: FSP084-DMAA1	
Driver Version	INF	10.1.1.36
	Graphics	21.20.16.4550
	Ethernet 1	12.15.22.6
	Ethernet 2	12.15.22.6
	Audio	6.0.1.7541
	USB3.0	10.0.16299.125

O.S.	Version	Feature Test	Result	Remarks
Microsoft Windows 10 Professional English 64bit	RS3 (1709)	Installation Boot, Shutdown, Reboot	Passed	UEFI mode

1.2 Ubuntu Configuration

CPU	Intel(R) Atom(TM) Processor E3950 @ 1.60GHz
Memory	Transcend TS9W9SESD-I DDR3L-1600 8GB [SEC chipset]
HDD	Transcend TS64EPTMM16-I 64GB
DVD-ROM	Pioneer DVR-XU01T
Power Supply	FSP GROUP INC. model: FSP084-DMAA1

O.S.	Kernel Version	Feature Test	Result	Remarks
Ubuntu 16.04.2 LTS 64bit	4.4	Installation Boot, Shutdown, Reboot	Passed	